

Seacoast Specialist Cars, LLC

174 Raymond Rd. Suite B

Candia, NH. 03034

Phone: 603-782-0870

INVOICE**838**

Org. Est. # 000869

Invoice from History

Printed Date: 01/14/2025

Work Completed: 12/31/2024**SEACOAST SPECIALIST CARS LLC**

174 RAYMOND ROAD SUITE B

Candia, NH 03034

Cellular 603-782-0870

2018 Porsche - Cayenne GTS - 3.6L, V6 (220CI) VIN(Not Availa

Lic # :

Odometer In : 70304

Odometer Out : 70577

VIN # : WP1AD2A25 JLA81029

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
REPAIR SET, WIRE 000 979 009EA	2.00	26.39	52.78	PLEASE PERFORM USED CAR CHECK AND ADVISE.	202.95
CONNECTOR HOUSING 1J0 972 483A	1.00	35.09	35.09	PERFORMED USED CAR CHECK. FOUND ITEMS OF CONCERN: -RIGHT SIDE INSIDE LIGHT ON TRUNK LID LENS MISSING -REAR BRAKES ARE AT 4MM. -RATTLE INSIDE VEHICLE NEAR GLOVE BOX AREA -RECOMMEND WIPER BLADES -OIL LEAKS. CLEANED ENGINE BAY. TEST DROVE VEHICLE. OIL LEAK IS SEEMS TO BE COMING FROM OIL PRESSURE SENSOR.	
MOBIL1 0W-40 Size: QUART 0W40	8.90	14.61	130.03		
OIL FILTER 0PB 115 466	1.00	30.49	30.49		
SEAL RING 946 107 322 75	1.00	9.22	9.22	CUSTOMER REQUESTS NEW HAMPSHIRE STATE INSPECTION	45.00
OIL DRAIN PLUG GASKET 900 123 106 30	1.00	0.61	0.61		
OIL PRESSURE SENDER 948 606 213 00	1.00	285.99	285.99	SALES DEPARTMENT STATES WARNING LIGHTS ARE ON IN DASH SCANNED VEHICLE. VEHICLE HAD MULTIPLE CODES STORED. IN DME, CODES P1537-OIL PRESSURE CONTROL, ABOVE UPPER LIMIT, P1152-OIL PRESSURE-REGULATING VALVE: ACTIVATION, P1149-OIL PRESSURE-REGULATING VALVE: POWER SUPPLY, AND P0341- BANK 1 INTAKE CAMSHAFT SENSOR. CHECKED CAMSHAFT SENSOR. FOUND SENSOR WIRING HARNESS HAS BEEN PINCHED AND ALL THREE WIRES ARE CUT. RECOMMEND WIRES BE REPAIRED. REPAIRED WIRES. CLEARED CODES AND TEST DROVE VEHICLE.	1,948.32
O-RING 999 707 575 40	1.00	8.66	8.66		
SEAL RING 900 123 144 30	1.00	1.90	1.90		
BOLT 9A7 008 130 00	2.00	1.74	3.48		
SOLENOID VALVE 946 107 113 60	1.00	538.91	538.91	VEHICLE ALSO HAD CODES FOR LEVEL CONTROL. 00024D-BODY ACCELERATION SENSOR FR, SHORT TO GROUND, 000349 PASM EMERGENCY MODE. REMOVED RIGHT FRONT ENGINE TRIM PANEL. FOUND MOUSE CHEWED THROUGH WIRING FOR ACCELERATION SENSOR. RECOMMEND WIRING BE REPAIRED.	
BOLT N 101 243 06	1.00	2.95	2.95		
BOLT N 101 243 06	19.00	1.73	32.87		
FLANGE 946 107 313 75	1.00	60.47	60.47	TEST DROVE VEHICLE. OIL PRESSURE WARNING CAME ON DASH. SCANNED VEHICLE. VEHICLE HAD THREE CODES FOR OIL PRESSURE RELIEF VALVE. CHECKED FOR POWER AND TO VALVE. VALVE HAS GOOD POWER. RECOMMEND NEW OIL PRESSURE RELIEF VALVE.	
POLLEN FILTER 958 819 631	1.00	50.46	50.46		
BRAKE FLUID BRAKE FLUID	1.00	16.45	16.45	PERFORM OIL CHANGE SERVICE	202.95
SPARK PLUG 999 170 235 90	6.00	23.54	141.24	REPLACE OIL PRESSURE SENDER	405.90
AIR FILTER 958 110 130 00	2.00	44.90	89.80	REPLACE OIL PRESSURE REGULATING VALVE	811.80
TRANSFER CASE FLUID 000 043 305 63	1.00	80.34	80.34	DRAINED ENGINE OIL. REMOVED AND REPLACED OIL PRESSURE CONTROL VALVE. REPLACED ALL SEALS. FILLED ENGINE OIL. NO LEAKS FOUND. TEST DROVE VEHICLE.	
Shop Supplies			34.95		
				PERFORM DETAIL	680.00
				UPGRADE TO MAJOR SERVICE	466.79

Visit us on the web: www.sscarsnh.comEmail Address: tvagi@sscarsnh.com

Service Advisor : Vagi, Tom, Tech : Kustos, Christopher 003; Rundlett, Max

Page 1 of 2

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr

Seacoast Specialist Cars, LLC

174 Raymond Rd. Suite B

Candia, NH. 03034

Phone: 603-782-0870

INVOICE**838**

Org. Est. # 000869

Invoice from History

Printed Date: 01/14/2025

Work Completed: 12/31/2024**SEACOAST SPECIALIST CARS LLC**

174 RAYMOND ROAD SUITE B

Candia, NH 03034

Cellular 603-782-0870

2018 Porsche - Cayenne GTS - 3.6L, V6 (220CI) VIN(Not Availa

Lic # :

Odometer In : 70304

Odometer Out : 70577

VIN # : WP1AD2A25 JLA81029

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
				REPLACED POLLEN AIR FILTER. TOPPED OFF FLUIDS.	
				REPLACE BRAKE FLUID	202.95
				PERFORMED BRAKE FLUID FLUSH.	
				REPLACE SPARK PLUGS	202.95
				REPLACED SPARK PLUGS. TORQUED TO PORSCHE SPECIFICATIONS.	
				REPLACE AIR FILTERS	101.48
				REPLACED ENGINE AIR FILTERS.	
				PERFORM WATER DRAIN MAINTENANCE	385.61
				-COWL DRAIN MAINTENANCE	
				-SUNROOF DRAIN	
				CLEANED OUT DRAINS. POURED WATER DOWN DRAINS.	
				DRAINS ARE WORKING AS DESIGNED.	
				REPLACE TRANSFER CASE FLUID	202.95
				REPLACED TRANSFER CASE FLUIDS.	
				CUSTOMER REQUESTS BALANCE WHEELS	199.95
				BALANCED WHEELS. TWO WHEELS WERE OUT OF BALANCE.	
				TORQUED WHEELS TO PORSCHE SPECIFICATIONS. SET TIRE PRESSURES.	

Org. Estimate 473.45 Revisions 5,051.87 Current Estimate 5,525.32

Revision # 1, Previous Estimate Amount: 473.45, Additional Cost: 740.88, Revised Estimate: 1214.33, Parts: \$300.03 Labor: \$405.90 Sublet: \$0.00
Taxes & Fees: \$34.95 Authorized by - , Date - 11/25/2024, Time - 5:07 PM, Initiated By - Shop, Written By - Vagi, TomRevision # 2, Previous Estimate Amount: 1214.33, Additional Cost: 1412.78, Revised Estimate: 2627.11, Parts: \$258.22 Labor: \$1177.11 Sublet: \$0.00
Taxes & Fees: \$-22.55 Authorized by - , Date - 11/25/2024, Time - 5:07 PM, Initiated By - Shop, Written By - Vagi, TomRevision # 3, Previous Estimate Amount: 2627.11, Additional Cost: 1488.49, Revised Estimate: 4115.60, Parts: \$641.74 Labor: \$811.80 Sublet: \$0.00
Taxes & Fees: \$34.95 Authorized by - , Date - 12/5/2024, Time - 3:04 PM, Initiated By - Shop, Written By - Vagi, TomRevision # 5, Previous Estimate Amount: 4851.86, Additional Cost: 673.46, Revised Estimate: 5525.32, Parts: \$-6.54 Labor: \$680.00 Sublet: \$0.00
Taxes & Fees: \$0.00 Authorized by - , Date - 12/19/2024, Time - 5:58 PM, Initiated By - Shop, Written By - Vagi, Tom

[Payments - X - N/A - \$7,666.29]

Labor:	6,059.60
Parts:	1,606.69
SubTotal:	7,666.29
Tax:	0.00
Total:	7,666.29
Bal Due:	\$0.00

Vehicle Received: 11/15/2024

Customer Number : 61

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one year or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. By signing this invoice, I agree that all charges are correct and legitimate.

Signature _____ Date _____

Visit us on the web: www.sscarsnh.comEmail Address: tvagi@sscarsnh.com

Service Advisor : Vagi, Tom, Tech : Kustos, Christopher 003; Rundlett, Max

Page 2 of 2

Copyright (c) 2025 Mitchell Repair Information Company, LLC invhrs 5.12.21kr